



21.07.2026 - Milan

New Software R58 TUNE Upgrade

fix a bug for alarm 112 (cleaning procedure)

Software

The new Master software versions is :

For Master control board :
Master SW : **RockyR58-119**

For the HMI Display board:
Display SW : **DWIN_SET**



USB setting

To update the machine, only a USB pen drive formatted FAT32 is required.
On the root of the pen drive place the following software files inside:

**Folder named «DWIN_SET»
RockyR58.119**


> Unità USB (D:) >				
↑↓ Ordina ≡ Visualizza ▾ △ Espelli ...				
☐	Nome	Ultima modifica	Tipo	Dimensione
	DWIN_SET	17/07/2026 15:38	Cartella di file	
	RockyR58-119.bin	17/07/2026 14:07	File BIN	105 KB

How to make the Update

- Turn OFF the machine. Be sure to have HMI display connected to the machine.
- Insert the USB pen drive containing the update file into the port at the left side of the machine.
- Turn ON the machine
- Wait 2 minutes until the HMI display to indicate that the USB drive should be removed
- Remove the USB pen drive



To verify that the software has been loaded correctly,
turn ON the machine and
FW DISPLAY 01.12
FW BOARD 1.19
should appear on the Display



Rocket Espresso

Via Achille Grandi 1,
20060 Truccazzano
Milan, Italy

Web: www.rocket-espresso.com

Social:   